

Chandler, February 12, 2026

## **USB CONNECTOR CHANGE NOTICE 1002-002-01100, 1002-002-01100-TR**

To whom it may concern,

Due to a tooling issue, we have re-tooled part number 1002-002-01100 and 1002-002-01100-TR. Products with a date code after 26/03 will be done with the new tooling which is very close to the original form, fit and function, but has some slight dimensional differences.

Please also review new drawings on our website:

- 1002-002-01100: [https://www.cnctech.us/pdfs/1002-002-01100\\_.pdf](https://www.cnctech.us/pdfs/1002-002-01100_.pdf)
- 1002-002-01100-TR: [https://www.cnctech.us/pdfs/1002-002-01100-TR\\_.pdf](https://www.cnctech.us/pdfs/1002-002-01100-TR_.pdf)

Regards,

H. Meyer  
CnC Tech